

NBP-10

Photo Inventory

~~(By Camera)~~ → BY STREAM REACH

Project: 08-3233

Group: BG + CM

Camera: OLYMPUS

This field sheet is to be completed AS photos are taken in the field. The intent is to force us to organize pictures taken on a camera basis. Fill out one sheet per camera (add sheets as needed). Only fill in Date/Reach/Location ID when you start in a new spatial or temporal location.

Date	Stream/Reach	Location ID	Photo #	Description
11/23/09	NBP-10	NEAR DOWNSTREAM END	(PB2300-) -22	TREE + LIMB DAM, ERODING BANK (SEE PB2300021 FOR DOWNSTREAM END OF NBP-10+11)
			23	ERODING (L) BANK
			24	EROSION (L) + (R) BANKS
			25	DEBRIS DAM @ OK BOW, RIVER BREAKING THROUGH OLD BANK @ TREES
			26	DEBRIS IN RIVER DOWNSTREAM FROM PARKING
			27	LOGGING STORMWATER OUTFALL AT S. END OF PARKING, RIPRAP + CONCRETE
			28	ANOTHER STORMWATER OUTFALL FROM PARKING
			29	CAMP STREET WITH PARKING IN BUFFER
		NEAR UPSTREAM END	30	CONDUIT CROSSING STREAM BELOW CAMPUS ROAD

COMMENTS:

NBP-11

Photo Inventory

~~(By Camera)~~ → BY STREAM REACH

Project: 08-3233

Group: BG + CM

Camera: OLYMPUS

This field sheet is to be completed AS photos are taken in the field. The intent is to force us to organize pictures taken on a camera basis. Fill out one sheet per camera (add sheets as needed). Only fill in Date/Reach/Location ID when you start in a new spatial or temporal location.

Date	Stream/Reach	Location ID	Photo #	Description
11/23/09	NBP-11	ABOVE REACH	(PB2300) - 13	CONCRETE BANK ABOVE RR CULVERT
		UPSTREAM END	14	LOOKING UPSTREAM AT CULVERT
			15	100' DOWNSTREAM FROM RR CULVERT
			16	MASH + DEBRIS DAM (BOTH COMMON)
			17	TYPICAL ERODED BANK ON (C)
			18	CULVERT UNDER MARKETWAY DRIVE
			19	DOWNSTREAM M.T. DRIVE CULVERT, LOW IN WATER
			20	MORE STABLE STRETCH BELOW M. TOWN
		DOWNSTREAM END	21	SILT-LADEN WATER ENTERING NORTH BRANCH

COMMENTS:

NBP-14

Photo Inventory

(By Camera) → BY STREAM REACH

Project: 08-3233

Group: BG+CM

Camera: OLYMPUS

This field sheet is to be completed AS photos are taken in the field. The intent is to force us to organize pictures taken on a camera basis. Fill out one sheet per camera (add sheets as needed). Only fill in Date/Reach/Location ID when you start in a new spatial or temporal location.

Date	Stream/Reach	Location ID	Photo #	Description
11/24/09	NBP-14	FIRST BEND ABOVE DOWNSTREAM END	ABANDONED 58	ESTATE + LAWN, (R) BANK
			59	(L) BANK ARMORED BY TREE, CHAIN LINK FENCE, IRON-CONTAMINATED SEEP (PIPES?)
			60	STONE REMAINS OF DAM OR CROSSING
			61	TWO 54" BROKEN PIPES (L) BANK (LOOKING UPSTREAM) NEAR END OF WOODLAND DR
			62	ENDING BANKS ABOVE 54" PIPES
			63	TRASH TRAPPED AT DESNIS DAM
			64	OUTFALL, (L) BANK (LOOKING UPSTREAM)
			65	FALLEN TREES + ENDING (R) BANK
			66	FALLING HEADWALL, (R) BANK
			67	TYPICAL RIFFLE
			68	DEW TREE, (R) BUFFER
		CLOSE TO UPSTREAM END	70	ESTATE + LAWN, (R) BANK, ABOVE STONE ABUTMENTS, ABANDONED BRIDGE

COMMENTS:

NBP-15

Photo Inventory

(By Camera) → BY STREAM REACH

Project: 08-3233

Group: B6+CM

Camera: OLYMPUS

This field sheet is to be completed AS photos are taken in the field. The intent is to force us to organize pictures taken on a camera basis. Fill out one sheet per camera (add sheets as needed). Only fill in Date/Reach/Location ID when you start in a new spatial or temporal location.

Date	Stream/Reach	Location ID	Photo #	Description
11/24/09	NBP-15	DOWNSTREAM END	P82400 49	STORMWATER HEADWALL + ASYLUM AVENUE BRIDGE
			50	STORMWATER OUTLET BELOW PARKING LOT, (L) BANK
			51	RESIDENTIAL ESTATE RETAINING WALLS, (R) BANK
			52	RIPARIAN WETLAND, (R) BANK
			53	HEADWALL + PIPE, (L) BANK
			54	OLD SWAGE AND EMBANK, (R) BANK
			55	ENDED SWAGE W/CONCRETE, (L) BANK
		UPSTREAM END	56	WETLANDS + TRIBUTARY (L) BANK
		UPSTREAM END	57	ENDING TOP OF ISLAND, (R) BANK

COMMENTS:

NBP-16

Photo Inventory

(By Camera) → BY STREAM REACH

Project: 08-3233

Group: BG + CM

Camera: OLYMPUS

This field sheet is to be completed AS photos are taken in the field. The intent is to force us to organize pictures taken on a camera basis. Fill out one sheet per camera (add sheets as needed). Only fill in Date/Reach/Location ID when you start in a new spatial or temporal location.

Date	Stream/Reach	Location ID	Photo #	Description
11/24/09	NBP-16	DOWNSTREAM END	PB2400 38	TERMINAL CULVERT, ARMORED BANKS
			39	ARMORED CHANNEL (RIPRAP), STEEP SLOPE (R) BANK
			40	SLOPE FAILURE + BROKEN PIPE, (R) BANK
			42	RIPRAPPED (L) BANK + SLOPE, ERODING (R) BANK
			43	ERODING (L) BANK + PIPE EXPOSED BY EROSION
			44	GABION WALL, (R) BANK, WITH CONCRETE STRUCTURE
			45	MALWAYS + WOOD DUCKS BY UNDERCUT BANK
			46	OUTFALL PIPE, (R) BANK
			47	CONCRETE STRUCTURE + ERODING (R) BANK
		NEAR UPSTREAM END	48	OUTFALL PIPE + HEADWALL (L) BANK, JUST BELOW ASYLUM AVE. BRIDGE

COMMENTS:

FYB-02

Photo Inventory

~~(By Camera)~~ → BY STREAM REACH

Project: 08-3233

Group: BG + CM

Camera: OLYMPUS

This field sheet is to be completed AS photos are taken in the field. The intent is to force us to organize pictures taken on a camera basis. Fill out one sheet per camera (add sheets as needed). Only fill in Date/Reach/Location ID when you start in a new spatial or temporal location.

Date	Stream/Reach	Location ID	Photo #	Description
11/24/09	FYB-02	DOWNSTREAM END	75	LOOKING UPSTREAM FROM MOUTH
			76	EROSION, TREES FALLING IN
			77	DEBRIS DAM
			78	ERODING BANKS, DEEP POOL
			79	PIPE, (R) BANK (HOUSING SIDE)
			80	ANOTHER DEBRIS DAM, WITH TRASH
			82	STORMWATER PIPE + TRASH (L) BANK (BELOW PARKING LOT)
		UPSTREAM END	83	CULVERT UNDER COTTAGE GROVE ROAD, LOOKING UPSTREAM
		UPSTREAM END	84	DOWNSTREAM FROM CULVERT

COMMENTS:

WBS-04

Photo Inventory

(By Camera) → BY STREAM REACH

Project: 08-3233

Group: BG+CM

Camera: OLYMPUS 2

This field sheet is to be completed AS photos are taken in the field. The intent is to force us to organize pictures taken on a camera basis. Fill out one sheet per camera (add sheets as needed). Only fill in Date/Reach/Location ID when you start in a new spatial or temporal location.

Date	Stream/Reach	Location ID	Photo #	Description
12/3/09	WBS-04	DOWNSTREAM END	20300 43	CULVERT UNDER BROWN STREET, WITH STORMWATER PIPE (R); STONE+DEBRIS DAM
			42	CATTAIL MARSH + FLOODED SECTION ABOVE STONE+DEBRIS DAM
			41	ANOTHER STONE + DEBRIS DAM
			40	STORMWATER PIPE FROM EQUIP. YARD
			39	FROM DRIVEWAY CROSSING
			38	DOUBLE DRIVEWAY CULVERTS
			37	STREAM IN CATTAIL MARSH, HORSE PASTURE ON (R)
			36	FOOTBRIDGE + DAM SPILLWAY + DOWNSTREAM
			35	BARRIER, ENDING (R) BANK OF NEWLY REBUILT POND
			34	SMALL BRIDGE AND REBUILT POND WITH UNPROTECTED SOIL PILES + BANKS
			32	CULVERT ABOVE SMALL BRIDGE, WITH POOL AND EQUIPMENT
			31	JUNK ACROSS, IN, AND ON BANK OF STREAM, POOL IN (R) BACKGROUND
			30	PHRAGMITES, MULTIFLOA NOSE, AND AUTUMN OLIVE ON BOTH BANKS
		UPSTREAM END	29	FROM CONFLUENCE

COMMENTS:

WBN-04

Photo Inventory

~~(By Camera)~~ → BY STREAM REACHProject: 08-3233Group: BG+CMCamera: OLYMPUS 2

This field sheet is to be completed AS photos are taken in the field. The intent is to force us to organize pictures taken on a camera basis. Fill out one sheet per camera (add sheets as needed). Only fill in Date/Reach/Location ID when you start in a new spatial or temporal location.

Date	Stream/Reach	Location ID	Photo #	Description
3 DEC 09	WBN-04	DOWNSTREAM END	PCO 300- 45	STREAM ENTERING CULVERT UNDER MUCKO ROAD
			46	SINUOUS CHANNEL + FLOODING IN FLOODPLAIN N. OF MUCKO ROAD
			47	COLLAPSING FOOTBRIDGE TO BOY SCOUT CABIN
			48	CONFLUENCE WITH TRIBUTARY ON (L)
			49	MEANDER IN MOSS HUB SKUNK LARBAGE FLOODPLAIN
			50	OLD CROSSING WITH BROKEN PIPE, OLD FARM DUMP IN BACKGROUND
			51	RESIDENTIAL YARD WITH UNDISTURBED BUFFER, (D) BANK
			52	ATV BRIDGE FROM SAME YARD
			53	MAN-MADE STONE BANK, SAME YARD
			54	TANKS IN STREAM AND ON (R) BANK
			55	VERY TRASHY YARD ON (L) BANK, FROM DOWNSTREAM END OF LONG CULVERT
			56	STREAM APPROACHING LONG CULVERT, UNDER 2 DRAWEWAYS AND LAWN BEHIND FENCE
			57	MOWN BUFFER (R) WITH JAPANESE KNOTWEED BOTH BANKS
			58	ROADSIDE CHANNEL WITH J. KNOTWEED, END OF CULVERT UNDER WOODLAND AVE.
		UPSTREAM END	59	CATTLE MARSH LEADING TO WOODLAND AVE CULVERT, BEHIND POND E. OF ROAD

COMMENTS:

WTR-02

Photo Inventory

(By Camera) → BY STREAM REACH

Project: 08-3233

Group: BG + CM

Camera: OLYMPUS 2

This field sheet is to be completed AS photos are taken in the field. The intent is to force us to organize pictures taken on a camera basis. Fill out one sheet per camera (add sheets as needed). Only fill in Date/Reach/Location ID when you start in a new spatial or temporal location.

Date	Stream/Reach	Location ID	Photo #	Description
12/8/09	WTR-02	DOWNSTREAM END	POBECO -64	CULVERT UNDER OLD FARM ROAD
			65	TRIBUTARY ON (R), SEDIMENT ON (L) ↑ SMALL
			66	OLD TIMBER BRIDGE (FOOTBRIDGE)
			67	SINOUS CHANNEL, NEW FILL AND PIPE ON (L) (NEW OFFICE BUILDING)
			68	FENCES + FALLEN TREES ACROSS STREAM, NEW BUILDING IN BACKGROUND
			69	ALMOST-EQUAL TRIBUTARY ON (R)
			70	RELATIVELY STABLE UNDER (L) BANK
			71	UNSTABLE BANK EROSION IN DOWNSTREAM UPSTREAM SLOPE
		UPSTREAM END	72	FIRM PIPE THROUGH DUDLEY POND DAM

COMMENTS:

FYB-03

Photo Inventory

~~(By Camera)~~ → BY STREAM REACH

Project: 08-3233

Group: BG+CM

Camera: OLYMPUS 1
+ DISPOSABLE

This field sheet is to be completed AS photos are taken in the field. The intent is to force us to organize pictures taken on a camera basis. Fill out one sheet per camera (add sheets as needed). Only fill in Date/Reach/Location ID when you start in a new spatial or temporal location.

Date	Stream/Reach	Location ID	Photo #	Description
11/30/09	FYB-03	DOWNSTREAM END	002	BANK EROSION + CULVERT UNDER COTTAGE GROVE ROAD
			003	TYPICAL SHAWB STREAM W/ALDEIS, DOGWOOD
			004	RIFLE WITH SAND BARS
			005	GRASSY NEW FLOODPLAIN BELOW OLD FLOODPLAIN (DOWNCUTTING?)
			006	PIPE + ERODED CHANNEL FROM SUBDIVISION, (A) BANK
			007	BANK EROSION AND SLOPE FAILURE (A)
			DISP-08	RIPRAP (B) BANK
		UPSTREAM END	DISP-09	RIPRAP + MULTIFURCA NOSE FROM RR BED

COMMENTS:

WBS-11

Photo Inventory

(By Camera) → BY STREAM REACH

Project: 08-3233

Group: GG+CM

Camera: DISPOSABLE

This field sheet is to be completed AS photos are taken in the field. The intent is to force us to organize pictures taken on a camera basis. Fill out one sheet per camera (add sheets as needed). Only fill in Date/Reach/Location ID when you start in a new spatial or temporal location.

Date	Stream/Reach	Location ID	Photo #	Description
11/30/09	WBS-11	DOWNSTREAM END	149300- 10	COVERED FOOTBRIDGE AT FORK IN CHANNEL (ALL FLOW TO (R))
			11	CULVERT FROM MEDICAL BLDG PARKING LOT
			12	BEDROCK SLOPE ON (R), BEDROCK AND GRAVEL STREAMBED
			13	(R) TRIBUTARY FROM (L) BANK
			14	EROSION AND SLOPE FAILURE (L) BANK BELOW GABION + RIPRAP SLOPE
			15	GABION, RIPRAP, + BLOCK ON (L) SLOPE
			16	(R) SLOPE FAILURE + RIPRAP NEAR BLOOMFIELD AVENUE
			17	COTTAGE GROVE ROAD CULVERTS
			18	TRIBUTARY (L), FROM (R) BANK
			19	OAKS ON ERODING (L) BANK
			20	ARCH CULVERT UNDER BLOOMFIELD AVE
			21	GOLF CART FOOTBRIDGE AND REMAINS OF DAM, BLOOMFIELD AVE. IN BACKGROUND
			22	TYPICAL STRETCH IN WOODS WEST OF GOLF COURSE

COMMENTS: DISCOLORATIONS FROM WET FILM, PHOTO AT UPSTREAM END RUINED

BHR-01

Photo Inventory

(By Camera) → BY STREAM REACH

Project: 08-3233

Group: BG+CM

Camera: OLYMPUS 2

This field sheet is to be completed AS photos are taken in the field. The intent is to force us to organize pictures taken on a camera basis. Fill out one sheet per camera (add sheets as needed). Only fill in Date/Reach/Location ID when you start in a new spatial or temporal location.

Date	Stream/Reach	Location ID	Photo #	Description
12/8/09	BHR-01	DOWNSTREAM PROXIMO- END	84	STREAM ENTERING CATTAIL POND
			85	ALDERS + PHRAGMITES ABOVE POND, STREAM CHANNEL DIFFUSE
			86	EXTENSIVE DUMPING (L) SLOPE BY ALVIN BUILDING
			87	TRIBUTARY (L) ABOVE ALVIN SLOPE
			88	ALDERSWAMP, ALVIN BLDG. IN BACKGROUND
			89	TYPICAL WOODED SECTION FROM OLD FARM ROAD
			90	STREAM ENTERING FARM RD. CULVERT, PART OF ABANDONED CAR ON (R)
			91	EXTENSIVE SEDIMENT DEPOSITION IN WETLAND, WASHOUT IN SLOPE FROM INDUSTRIAL SITE (R)
			92	IRON STAINS, SEDIMENT DEPOSITION, AND RAILROAD TRACKS SOUTH OF ROUTE 187
			93	SEDIMENT FROM RTE 187 CULVERT, BARE TRUCKLE OF FLOW, COON TRACKS
			94	SEDIMENTED STREAM FROM RTE 187
			95	RTE 187 CULVERT INVERT, PHRAGMITES AT EDGE OF POND
			96	CENTER OF POND
		UPSTREAM END	97	NORTH END OF POND, SEDGE MARSH, NO STREAMS FLOWING INTO POND

COMMENTS: NO STREAM, NO CHANNEL NORTH OF ROUTE 187

BHR-02

Photo Inventory

(By Camera) → BY STREAM REACH

Project: 08-3233

Group: BG+CM

Camera: OLYMPUS 2

This field sheet is to be completed AS photos are taken in the field. The intent is to force us to organize pictures taken on a camera basis. Fill out one sheet per camera (add sheets as needed). Only fill in Date/Reach/Location ID when you start in a new spatial or temporal location.

Date	Stream/Reach	Location ID	Photo #	Description
12/8/09	BHR-02	DOWNSTREAM END	76	STREAM ENTERING CULVERT UNDER WEST DUDLEYTOWN ROAD
			77	NEARLY EQUAL TRIBUTARY ON (L)
			78	TYPICAL FORESTED STRETCH W/ SAND BAR
			79	TRIBUTARY (R)
			80	BANK EROSION (MINOR) ON (L)
			81	PHRAGMITES AND BARRELS (R) BANK
			82	MORE BARRELS + TRASH (R) BUFFER (SAME DUMP)
		UPSTREAM END	83	2 PIPES IN CATTAIL POND DAM

COMMENTS:

